
I.



STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES AS A WARRING DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340

Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

	ORDERVILLE, UTAH 84758	
7.	Permanent Address: TETLA SEPTARIANS	
6.	Name of Operator or Company:	
5.	Mineral(s) Mined:Septarians	
	1/4,1/4, Section, Township, Range	
	1/4,1/4, Section, Township, Range	
	1/4,1/4, Section, Township, Range	
4.	Legal Description (Location of Lands Affected):	
3.	Mine Name: Tetla Septarians ML41355, ML19890, & ML27866 Township 40 So, Range 7 Wst, SLB&M Sc. 31 & 36 & 31 respectavly	
2.	DOGM File Number (original notice): 5/025/006	
1.	Report Time Period: From (mo./yr.) Jan. 90 To (mo./yr.) Dec. 90	
<u>GENI</u>	ERAL INFORMATION	

8.	Company Representative (or designated operator):			
	Name: Gerald W. Berry			
	Title: Owner			
	Address:Same			
	Phone:			
	Please check if any of the above information has changed since previous year.			
II.	MINING AND RECLAMATION Was the mine active during the past year? Yes ▼ No □			
1.				
2.	If active, how much ore or mineral was mined?Approx 20 tons			
3.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, volume of material moved, and the acreage affected.			
	Four separate areas of five yards wide by fifty yards long or less were opened by dozer and track hoe. Anywhere from five to 20 feet of overburden was remove from above those areas. Total before reclaimation is under one acre. Once the areas are leveled and reshaped it could be around two arces or slightly less.			
4.	Briefly describe the reclamation work performed during the past year. This description should include acreage reclaimed, methods employed, and an evaluation of the results. In ML 41355 all areas were back filled and leveled. In ML 19890 leveling was started but because of adverse weather it has been suspended till such time as weather allows us to start again. Usually early spring at the latest. At that time both areas will be reseaded.			
5.	What was the total unreclaimed acreage at years end? less than 1 acr			

6.	Not known at this time wi ML 41355 of about 10 yds	clamation planned for the upcoming year. th the exception of an area in wide by 20 yards long that we on over the past three years t a time.			
NOTE:	Section III., "Additional Informati	on" applies only to large mining operations.			
III. <u>ADDITIO</u>	NAL INFORMATION				
1.	An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.				
2.	Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.				
IV. <u>SIGNATU</u>	JRE REQUIREMENT				
I hereby certify that the foregoing is true and correct.					
	Name (Typed or Print):	Gerald W. Berry			
	Title of Operator:	Owner			
	Signature of Operator:				
	Date: Jan 9, 1991				
jb MNMR-AR					